

PERKINS 3 CYL ENGINE PARTS

CIP PARTS Phone 713 864 7084 Fax 713 864 5190

3 CYLINDER ENGINES MADE BY PERKINS

| BUILD LIST | SIZE | FUEL | REMARKS |
|-------------------|-------------|-------------|--------------------|
| CD00204 | 152 | DSL | Indirect Injection |
| CD00228 | 152 | DSL | Indirect Injection |
| CD00229 | 152 | DSL | Indirect Injection |
| CD00230 | 152 | DSL | Indirect Injection |
| CD20166 | 152 | DSL | Indirect Injection |
| CD20691 | 152 | DSL | Indirect Injection |
| CD22096 | 152 | DSL | Indirect Injection |
| CE08705 | 152 | DSL | Indirect Injection |
| CE21575 | 152 | DSL | Indirect Injection |
| CE21675 | 152 | DSL | Indirect Injection |
| CE21899 | 152 | DSL | Indirect Injection |
| CE22236 | 152 | DSL | Indirect Injection |
| CE22311 | 152 | DSL | Indirect Injection |
| CE22438 | 152 | DSL | Indirect Injection |
| CE22488 | 152 | DSL | Indirect Injection |
| CE22528 | 152 | DSL | Indirect Injection |
| CE22651 | 152 | DSL | Indirect Injection |
| CE22666 | 152 | DSL | Indirect Injection |

| | | | |
|----------------|-----|-----|--------------------|
| CE31048 | 152 | DSL | Indirect Injection |
| CE31064 | 152 | DSL | Indirect Injection |
| CE31089 | 152 | DSL | Indirect Injection |
| CE31106 | 152 | DSL | Indirect Injection |
| CE31115 | 152 | DSL | Indirect Injection |
| CE31116 | 152 | DSL | Indirect Injection |
| CE31133 | 152 | DSL | Indirect Injection |
| CE31138 | 152 | DSL | Indirect Injection |
| CE31144 | 152 | DSL | Indirect Injection |
| CE31161 | 152 | DSL | Indirect Injection |
| CE31168 | 152 | DSL | Indirect Injection |
| CE31182 | 152 | DSL | Indirect Injection |
| CE31183 | 152 | DSL | Indirect Injection |
| CE31184 | 152 | DSL | Direct Injection |
| CE31216 | 152 | DSL | After 06/30/93 |
| CE31222 | 152 | DSL | After 06/30/93 |
| CE50333 | 152 | DSL | Direct Injection |
| CE70021 | 152 | DSL | Direct Injection |
| CE70262 | 152 | DSL | Direct Injection |
| CE95231 | 152 | DSL | Indirect Injection |
| CM33496 | 152 | DSL | Cast Flanged Liner |
| CM33513 | 152 | DSL | Cast Flanged Liner |
| CM50168 | 152 | DSL | Cast Flanged Liner |

| | | | |
|----------------|-----|-----|---------------------------|
| CM50170 | 152 | DSL | Cast Flanged Liner |
| CM50184 | 152 | DSL | Cast Flanged Liner |
| CM50186 | 152 | DSL | Cast Flanged Liner |
| CM51029 | 152 | DSL | Cast Flanged Liner |
| CN31157 | 152 | DSL | 3 Ring dish Bowl |
| CN31158 | 152 | DSL | 3 Ring dish Bowl |
| CN31185 | 152 | DSL | 3 Ring dish Bowl |
| CN31187 | 152 | DSL | 3 Ring dish Bowl |
| CN31195 | 152 | DSL | 3 Ring Radiused Dish Bowl |
| CN31196 | 152 | DSL | 3 Ring Radiused Dish Bowl |
| CN31198 | 152 | DSL | 3 Ring Radiused Dish Bowl |
| CN31219 | 152 | DSL | Thru ESN U983573c |
| CN31225 | 152 | DSL | 3 Ring Radiused Dish Bowl |
| CN31252 | 152 | DSL | Thru ESN U983573C |
| CN31255 | 152 | DSL | Thru ESN U983573C |
| CP31292 | 165 | DSL | Naturally Aspirated |
| CP31447 | 165 | DSL | Naturally Aspirated |
| CP31448 | 165 | DSL | Naturally Aspirated |
| CP50625 | 165 | DSL | Naturally Aspirated |
| CP50627 | 165 | DSL | Naturally Aspirated |
| CP80820 | 165 | DSL | Naturally Aspirated |
| CP80906 | 165 | DSL | Naturally Aspirated |

| | | | |
|----------------|-----|-----|---------------------|
| CP81120 | 165 | DSL | Naturally Aspirated |
| CP81241 | 165 | DSL | Naturally Aspirated |
| CR31293 | 165 | DSL | Turbocharged |
| CR31357 | 165 | DSL | Turbocharged |
| CR50624 | 165 | DSL | Turbocharged |
| CR50626 | 165 | DSL | Turbocharged |
| CR80966 | 165 | DSL | Turbocharged |
| CR81242 | 165 | DSL | Turbocharged |
| CR81316 | 165 | DSL | Turbocharged |
| DC38027 | 202 | DSL | Natural Aspirated |
| DC38077 | 202 | DSL | Natural Aspirated |
| DD37992 | 202 | DSL | Turbocharged |
| DD38078 | 202 | DSL | Turbocharged |